

State of New Mexico
Energy, Minerals and Natural Resources Department OCT 25 2017
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

RECEIVED

Operator Name AVRA	*API Number 30-025-07329
Property Name Charleia Taylor	Well No. 1

7. Surface Location

UL - Lot I	Section 11	Township 18S	Range 38E	Feet from 1980	N/S Line S	Feet From 660	E/W Line E	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒ NO ☒	SHUT-IN YES ☒ NO ☒	INJ ☒	INJECTOR ☒ SWD ☒	PRODUCER OIL ☒ GAS ☒	DATE 10/25/17
---	---	---	---	---	-------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure				1200	1200
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☐
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Failure - Communication Prod csg + Tbg
Witnessed By Clay Tipton - Concealed
Failure

For Record Only

Signature:	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date: 10/25/17	Phone:
Witness: [Signature]	

INSTRUCTIONS ON BACK OF THIS FORM