

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name MATADOR Production		API Number 30-025-26547 ✓
Property Name Antelope Ridge 24 SWD		Well No. #1 ✓

Surface Location									
UL - Lot K	Section 24	Township 23s	Range 34E		Feet from 1980	N/S Line S	Feet From 1980	E/W Line W	County LEA

Well Status								
TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD	PRODUCER OIL	GAS	DATE 10-27-17

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	450
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Pump Down

Signature: M. H. Vais		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test	
E-mail Address:			
Date:	Phone:		
Witness: Gary Robinson			

575-399-3220

INSTRUCTIONS ON BACK OF THIS FORM