

NOV 08 2017

RECEIVED

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office
BRADENHEAD TEST REPORT

Operator Name LEGACY RESERVES OPERATING LP		API Number 30-025-11141	
Property Name COOPER JAL UNIT		Well No. 116	

Surface Location									
UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County	
M	18	24S	37E	660	S	660	W	LEA	



Well Status										
TA'D WELL	SHUT-IN	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE			
YES <input checked="" type="checkbox"/>	NO <input checked="" type="checkbox"/>	NO <input checked="" type="checkbox"/>	NO <input checked="" type="checkbox"/>	INJ <input checked="" type="checkbox"/>				10/6/17		

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	580				
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR <input checked="" type="checkbox"/>
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

A Gas

Signature: 	OIL CONSERVATION DIVISION
Printed name: STEVEN DITTMAN	Entered into RBDMS
Title: WELL TECH	Re-test 
E-mail Address: sdittman@legacylp.com	
Date: 10/6/17	
Phone: 432-312-4757	
Witness:	