

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

NOV 13 2017

RECEIVED

BRADENHEAD TEST REPORT

Operator Name <u>Legacy Reserve Operations LP</u>	API Number <u>3002510607</u>
Property Name <u>SPAV</u>	Well No. <u>27</u>

2. Surface Location

UL - Lot <u>1C</u>	Section <u>3</u>	Township <u>33S</u>	Range <u>37E</u>	Feet from <u>1980</u>	N/S Line <u>S</u>	Feet From <u>1980</u>	E/W Line <u>W</u>	County <u>Leg</u>
-----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well-Status

TA'D WELL ☒ YES ☐ NO	SHUT-IN ☐ YES ☒ NO	INJECTOR ☐ INJ ☐ SWD	PRODUCER ☒ OIL ☐ GAS	DATE <u>11/7/17</u>
--	--	---	--	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	<u>Q</u>			<u>180</u>	<u>Q</u>
Flow Characteristics					
Puff	☒ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	☒ Y ☐ N	CO2 ☐
Steady Flow	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	☒ Y ☐ N	WTR ☐
Surges	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	GAS ☐
Down to nothing	☒ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	☒ Y ☐ N	Type of Fluid
Gas or Oil	☒ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	Injected for
Water	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	☒ Y ☐ N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

D blew down to Q in 3 seconds - guts

Signature: <u>Diane Dally</u>	OIL CONSERVATION DIVISION
Printed name: <u>J. P. Dally</u>	Entered into RBDMS
Title: <u>Prod. Eval. Mgr.</u>	Re-test
E-mail Address:	
Date: <u>11/7/17</u>	
Phone:	
Witness:	