Submit I Copy To Appropriate District Office	State of New M		Form C-103		
<u>District 1</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Na	tural Resources	Revised July 18, 2013 WELL API NO.		
District II (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DEVISION District III (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. Francis Dr. District IV (505) 476-3460			30-025-32016		
District III - (505) 334-6178	1220 South St. Fr	ancis Dr.S	5. Indicate Type of Lease STATE X FEE		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476-3460	Santa Fe, NM	87505	6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM	D	2017			
87505 SUNDRY NOTI	CES AND REPORTS ON WEL	60.	7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			NEW MEXICO 'M' STATE		
1. Type of Well: Oil Well	Gas Well 🔲 Other		8. Well Number 9		
2. Name of Operator CHEVRON U.S.A. INC.		A	9. OGRID Number 4323		
 Address of Operator 6301 DEAUVILLE BLVD, MIDLAND, TX 79706 			10. Pool name or Wildcat VACUUM DRINKARD		
4. Well Location					
Unit LetterC:660feet from theNORTH line and2310feet from theWESTline					
Section	I Township 18-S	Range 34	-E NMPM County LEA		
	11. Elevation (Show whether D	R, RKB, RT, GR, etc.)			
	3,994' (GL)				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
	PLUG AND ABANDON	REMEDIAL WOR	SEQUENT REPORT OF: K 🛛 🛛 ALTERING CASING 🗌		
	CHANGE PLANS	COMMENCE DRI			
PULL OR ALTER CASING		CASING/CEMENT			
DOWNHOLE COMMINGLE					
CLOSED-LOOP SYSTEM		OTUED	-		
OTHER:	MIT REPAIR	OTHER:			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
Workover Summary: 10/11/17-11/3/17					
 MIRU. TOH and LD rodstring. Release TAC & POOH w/ tubing. RIH and set RBP @ 6,800'. Tested casing to 550 psi and lost 100 psi in 30 minutes Isolated casing leak from 4757-4787'. Ran CIL/CBL. Pump 5.1 bbls of class C cement to spot balanced plug from 4,864-4,621'. Pump 1.3 bbls & pressured up to 700#s with no leakoff Cleanout cement from 4,705-4,864'. Pressured up to 550 psi for 30 minutes, good test. Remove RBP. RIH w/ tubing and new BHA. RIH w/ rods & RTP. 					
Updated WBD is below.					
Spud Date:	Rig Release	Date:			
I hereby certify that the information	above is true and complete to the	best of my knowledg	e and belief.		
SIGNATURE TITLE_Production Engineer DATE11/16/17					
Type or print name _Michael Stewart E-mail address:michael.stewart@chevron.com PHONE: _432-687-7431					
APPROVED BY: Malus France AO/I DATE 11/20/2017 Conditions of Approval (if any):					

State	New Mexico
County	Lea
Surface Location	660FNL 2310FWL
-	Sec 1, R-34E, T-18S
-	Ltr C

CASING DETAIL	
Surface Csg.	
Size:	8-5/8"
Wt.:	24# WC-50
Set @:	1470'
Sxs cmt:	650 sx class "C"
TOC:	Surface
Hole Size:	11"
Production Csg.	
Size:	5-1/2"
Wt.:	17# L-80, WC-50, WC-70
Set @:	8100'
Sxs Cmt:	1825sx class "H"
TOC:	
Hole Size:	7-7/8"

NM M State 9_WBD_Updated.xls

WELLBORE DIAGRAM New Mexico "M" #9 WELL ID INFORMATION
 Lease Name
 New Mexico State "M" #9

 Field
 Vacuum Drinkard, Vac Blinebry
 Drinkard & Blinebry QU3257 Reservoir Ref # API # 30-025-32016 i Cmt Sqz 4,757-4787' **Blinebry perfs** -----E = 6850-6920' **Drinkard perforations** 7477-7858' PBTD: 8053' TD: 8100'

KB:

DF: GL: <u>3994'</u> Spud Date: <u>1/25/1994</u> Compl. Date: <u>2/15/1994</u>

4008'

11/16/2017