HOBBS OCD

Submit One Copy To Appropriate District 3 0 2017 State of New Mexico	Form C-103
	Revised November 3, 2011 WELL API NO.
District I 811 S. First St., Artesia, NM 88210 Energy, Minerals and Natural Resources Energy, Minerals and Natural Resources SECEMENT SERVATION DIVISION	30-025-03881
	5. Indicate Type of Lease
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410	STATE FEE
District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	West Lovington Unit
PROPOSALS.)	0 11/-1131 1
Type of Well: ☐ Oil Well ☐ Gas Well ✓ Other: Injection Name of Operator	9. OGRID Number #33
CHEVRON U S A INC	241333
3. Address of Operator	10. Pool name or Wildcat
6301 Deauville Blvd Midland, Texas 79706	Lovington Upper SA West
4. Well Location	
	feet from the East line NMPM County LEA
11. Elevation (Show whether DR, RKB, RT, GR, etc.,	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	
TEMPORARILY ABANDON	
OTHER:	1308
✓ Location is re	eady for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly a	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the following:	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER	OHAPTED LOCATION OF UNIT
LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN	
STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other	
production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
Anchors, dead men, the downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules	
and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and	
location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be	
removed.)	
All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow	
✓ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluilines and pipelines.	ids have been removed from non-retrieved flow
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines ha	we been removed from lease and well location,
except for utility's distribution infrastructure.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
EWIR, Bryce Digitally signed by EWIR, Bryce Wagoner	
SIGNATURE: Wagoner Date: 2017.11.27 10:15:41 - 06:00' TITLE: FIELD SITE MANAGER	DATE: 11/27/2017
TYPE OR PRINT NAME Bryce Wagoner E-MAIL: EWIR@chevron.com	PHONE: (928)241-1862
For State Use Only	
APPROVED	1 1
BY: Washington TITLE P.E.S.	DATE 11/30/2017
Conditions of Annoval (if any):	