

FLARE INSPECTION

Continental Resources
LEASE OR FACILITY NAME Merchant Livestock 25 ST. Com.

WELL # 2H API# 30-025 - 41350

U.L. C SEC 25 T 22S R 34E

FOOTAGE 40 N/S 1700 E/W (W)

IS A FLARE STACK PRESENT? YES NO

IS FLARE ACTIVE? YES NO

IS GAS TO FLARE METERED? YES NO

AREA AROUND FLARE CLEARED? YES NO

ENVIRONMENTAL CONCERNS _____

IS VRU PRESENT? YES NO

IS VRU ACTIVE? YES NO

COMMENTS 2 Batt. on location - 1 combustor takes Tank vapors from back Batt.

INSPECTOR Gary Polinson DATE 1-16-18