

FLARE INSPECTION

Centennial Resources

LEASE OR FACILITY NAME Merchant Livestock ³⁰ ~~ST~~ #

WELL # 2H API# 30-025-41676

U.L. C SEC 30 T 22s R 35E

FOOTAGE 33 (N) S 2260 E (W)

IS A FLARE STACK PRESENT? YES (NO)

IS FLARE ACTIVE? YES NO

IS GAS TO FLARE METERED? YES NO

AREA AROUND FLARE CLEARED? YES NO

ENVIRONMENTAL CONCERNS _____

IS VRU PRESENT? YES (NO)

IS VRU ACTIVE? YES NO

COMMENTS 2-Batt. on location - 1 combustor for
both tank vapors

INSPECTOR Greg Coleman DATE 1-16-12