

FLARE INSPECTION

BTA

LEASE OR FACILITY NAME Chis0 14 ST 8711 #3H

WELL # 3H API# 30-025-43614

U.L. P SEC 14 T 22S R 34E

FOOTAGE 230 N  S 950  W

IS A FLARE STACK PRESENT? YES  NO

IS FLARE ACTIVE? YES NO

IS GAS TO FLARE METERED? YES  NO

AREA AROUND FLARE CLEARED? YES  NO

ENVIRONMENTAL CONCERNS Gas is going to sales

IS VRU PRESENT? YES NO

IS VRU ACTIVE? YES NO

COMMENTS

Has combustor on tank vapors

INSPECTOR Shrey Robinson DATE 1-22-18