

HOBBS OCD  
JAN 23 2018  
RECEIVED

### FLARE INSPECTION

Murchison  
LEASE OR FACILITY NAME Bettis 20 ST. Com

WELL # 2H API# 30-025 - 41436

U.L. P SEC 20 T 24s R 33E

FOOTAGE 200 N  S 940  W

IS A FLARE STACK PRESENT?  YES NO

IS FLARE ACTIVE? YES  NO

IS GAS TO FLARE METERED?  YES NO

AREA AROUND FLARE CLEARED?  YES NO

ENVIRONMENTAL CONCERNS Prod gas going to sales via  
Compressor

IS VRU PRESENT? YES  NO

IS VRU ACTIVE? YES NO

COMMENTS Condensate being used on tank vapors

INSPECTOR Gary Robinson DATE 1-23-18