

HO
JAN 31 2018
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name TARGA MIDSTREAM SERVICES LLC		API Number 30-025-40002-0000 43470
Property Name MONUMENT AGI		Well No. 001 002

7. Surface Location

UL - Lot O	Section 36	Township 19-S	Range 36-E	Feet from 662-685	N/S Line S	Feet From 2513	E/W Line E	County LEA
----------------------	----------------------	-------------------------	----------------------	-----------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D Well YES NO	SHUT-IN YES NO	INJECTOR INJ SWD	PRODUCER OIL GAS	DATE 1-31-18
-----------------------------------	---------------------------------	-----------------------------------	-----------------------------------	------------------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	11.8	20.5	—	0	2110
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 _____
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR _____
Surges	Y / N	Y / N	Y / N	Y / N	GAS _____
Down to nothing	Y / N	Y / N	Y / N	Y / N	If applicable type
Gas or Oil	Y / N	Y / N	Y / N	Y / N	fluid injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

ELECTRONIC READINGS & MONITOR THROUGH TEST SUPP & ENT
Put 250# back on prod csg after test

Signature:		OIL CONSERVATION DIVISION
Printed name:		Entered into RBDMS
Title:		Re-test
E-mail Address:		
Date: 1-31-18	Phone:	
Witness: KERRY FORTNER-OCD 575-399-3221		