

HOBBS OCD

FEB 06 2013

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chertron	API Number 30-025-29971
Property Name W. TEAS YATES	Well No. 912

1. Surface Location									
UL - Lot E	Section 9	Township 20s	Range 33E		Feet from 1980	N/S Line N	Feet From 660	E/W Line W	County LEA

Well Status								
TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD	PRODUCER OIL	GAS	DATE 2-6-18

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	0
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Pump Down - line leak

Signature: Braxton Bats	OIL CONSERVATION DIVISION
Printed name: Braxton Bats	Entered into RBDMS
Title: PS	Re-test
E-mail Address: Bypu@chertron.com	
Date: 2/6/18	
Phone: 432-553-5184	
Witness: Larry Robinson	

575-399-3220

INSTRUCTIONS ON BACK OF THIS FORM