

HOBBS OCD

FEB 06 2013

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Cherron	API Number 30-025-31896 ✓
Property Name W. TEAS YATES	Well No. 921 ✓

7. Surface Location									
UL - Lot C	Section 9	Township 20s	Range 33E	Feet from 230	N/S Line W	Feet from 2310	E/W Line W	County LEA	

Well Status									
TA'D WELL YES	NO	SHUT-IN YES	NO	INJ	INJECTOR SWD	PRODUCER OIL	GAS	DATE 2-6-18	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	0
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

PUMP DOWN - Line repairs

Signature: Braden But	OIL CONSERVATION DIVISION
Printed name: Braden But	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date:	
Phone:	
Witness: Gary Robinson	

575-399-3200

INSTRUCTIONS ON BACK OF THIS FORM