

HOBBS OCD

FEB 06 2018

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron		API Number 30-025-32032 ✓
Property Name W TEAS YATES		Well No. 433 ✓

7. Surface Location

UL - Lot J	Section 4	Township 20S	Range 33E	Feet from 1650	N/S Line S	Feet From 1980	E/W Line E	County LEA
----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

YES	TA'D WELL ☒ NO ☐ YES	SHUT-IN ☒ NO ☐ YES	INJECTOR ☒ INJ ☐ SWD	PRODUCER ☐ OIL ☐ GAS	DATE 2-6-18
-----	--	--	--	---	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	NA	NA	0	0
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

PUMP Down - line repairs

Signature: Bradley		OIL CONSERVATION DIVISION	
Printed name: Bradley		Entered into RBDMS	
Title:		Re-test JK	
E-mail Address:			
Date:	Phone:		
Witness: Gary Robinson			

575-399-3220

INSTRUCTIONS ON BACK OF THIS FORM