

HOBBS OCD

FEB 06 2013

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron	API Number 30-025-32217
Property Name W. TEAS YATES	Well No. 941

1. Surface Location									
UL - Lot A	Section 9	Township 20s	Range 33E		Feet from 330	N/S Line N	Feet From 990	E/W Line E	County LEA

Well Status									
TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD	PRODUCER OIL	GAS	DATE 2-6-18	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csing	(E)Tubing
Pressure	0	N/A	N/A	0	0
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ✓
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Pump Down - line ~~break~~ repairs

Signature: [Signature]	OIL CONSERVATION DIVISION
Printed name: Brandon Bats	Entered into RBDMS
Title:	Re-test [Signature]
E-mail Address:	
Date:	
Phone:	
Witness: Gary Robinson	

575-399-3220

INSTRUCTIONS ON BACK OF THIS FORM