District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

HOBBS OCD
FEB 07 2018
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name	API Number
Chevron	30-025-23031

Property Name	Well No.
Quail Queen	#8

Surface Location

UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
K	11	19s	34E		2080	S	1980	W	LEA

Well Status

TA'D WELL		SHUT-IN		INJECTOR		PRODUCER		DATE
YES	NO	YES	NO	INJ	SWD	OIL	GAS	2-7-18

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0	N/A	N/A	0	0
Flow Characteristics					CO2 ___ WTR ___ GAS ___ Type of Fluid Injected for Waterflood if applies.
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Braxton Bath		OIL CONSERVATION DIVISION
Printed name: Braxton Bath		Entered into RBDMS
Title:		Re-test
E-mail Address:		
Date:	Phone:	
	Witness: Gary Robertson 575-399-3220	

INSTRUCTIONS ON BACK OF THIS FORM