

HOBBS OCD

FEB 07 2013

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron		API Number 30-025-26221	
Property Name Quail Queen		Well No. #31	

Surface Location

UL - Lot I	Section 11	Township 19s	Range 34e	Feet from 1841	N/S Line S	Feet From 759	E/W Line E	County 2-7-18
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	-------------------------

Well Status

☒ YES	TA'D WELL	NO	☒ YES	SHUT-IN	NO	☒ INJ	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE 2-7-18
--------------------------------------	-----------	----	--------------------------------------	---------	----	--------------------------------------	----------	-----	-----	----------	-----	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	0
Flow Characteristics					
Pull	Y / ☒ N	Y / N	Y / N	☒ / N	CO2 ___
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / ☒ N	WTR ___
Surges	Y / ☒ N	Y / N	Y / N	Y / ☒ N	GAS ___
Down to nothing	☒ / N	Y / N	Y / N	☒ / N	Type of Fluid
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / ☒ N	Injected for
Water	Y / ☒ N	Y / N	Y / N	Y / ☒ N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Prod. csg. slight water

[Handwritten signature]

Signature: Braxton Bate		OIL CONSERVATION DIVISION	
Printed name: Braxton Bate		Entered into RBDMS	
Title:		Re-test <i>[Handwritten signature]</i>	
E-mail Address:			
Date:	Phone:		
Witness: Gary Robinson			

575-399-3220

INSTRUCTIONS ON BACK OF THIS FORM