Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office	Energy, Minerals and Natural Reso	
District I 1625 N. French Dr., Hobbs, NM 88240	shorgy, ivinicials and i valuatal icoso	WELL API NO.
District II	OIL CONSERVATION DIVISI	ON 30-025-31210
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE FEE
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Dana 1 0, 14141 07505	6. State Oil & Gas Lease No. V-3306
87505 SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		Cerca AIX State
1. Type of Well: Oil Well Gas Well Other P&A		8. Well Number
2. Name of Operator		9. OGRID Number
2. Name of Operator Yates Petroleum Corporation		9. OGRID Number 025575
3. Address of Operator		10. Pool name or Wildcat
105 S. 4 th Street, Artesia, NM 88210		Saunders, East; Permo Penn
4. Well Location		
Unit Letter M: 660 feet from the South line and 810 feet from the West line		
Section 4	Township 14S Range	34E NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
Pit or Below-grade Tank Application or Closure		
		CID N/A Disa 6
		rell N/A Distance from nearest surface water N/A
	Below-Grade Tank: Volume N/A	bbls; Construction Material N/A
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON 🔲 CHA	ANGE PLANS 🔲 COMME	ENCE DRILLING OPNS.
PULL OR ALTER CASING MUI	_TIPLE COMPL	G/CEMENT JOB
OTHER:	☐ OTHER	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated that		
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Approved as to plugging of the Well Rose.		
or recompletion. Approved as to plugging of the Well Bore. Liability under bond is retained until		
	surface restoration is complete	
4-5-06 MIRU. ND WH. NU BOP.	surface restoration is complete	a
4-10-06 POOH w/tubing. No perf sub or seating nipple. Run in hole w/gauge ring to 60'. Pumped 20 bbls fresh water. Run gauge ring		
to 2050'. Pumped 20 bbls. Tagged @ 2080'. Pumped 100 gals. Tagged @ 8865'. Pumped 50 bbls. Tagged @ 8865'. POOH.		
4-11-06 RIH to 8886'. Worked and washed for 2.5 hrs. Called E.L. Gonzales w/OCD. Ok'd plug. Spotted 30 sx @ 8886'. WOC. 4-12-06 Tagged @) 8886'. Spotted 30 sx @ 8886'. WOC. Tagged @ 8530'. Pumped 10# mud. Did not circulate. Spotted 25 sx 8041-		
7801'. PUH and spotted 25 sx @ 5863'.		
	o 4433' and spotted 25 sx. WOC. Tag	ged @ 4196'. Perforated @ 2906'. RIH to 2883'.
Spotted 30 sx. WOC.		
4-14-06 RIH and tagged @ 2680'. Perforated @ 480'. Spotted 30 sx. WOC. Tagged @ 360'. Perforated @ 60'. Squeezed w/25 sx.		
Cut off wellhead, installed marker and cleaned up location.		
WELL IS PLUGGED AND ABANDONED. FINAL REPORT.		
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-		
grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan .		
SIGNATURE TITLE Regulatory Compliance Technician DATE 4-19-06		
Type or print name Stormi Davis E-mail address: stormid@ypcnm.com Telephone No. 505-748-1471		
For State Use Only		
APPROVED BY: Lay W. WINDOC FIELD REPRESENTATIVE HISTAFF MANAGER DATE		
Conditions of Approval (if any)		
1 1		