

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office  
BRADENHEAD TEST REPORT

HOBBS OCD  
MAR 02 2018  
RECEIVED

|                                           |                          |
|-------------------------------------------|--------------------------|
| Operator Name<br>Cross Timber Energy, LLC | API Number<br>3002522942 |
| Property Name<br>North Vacuum ABO Unit    | Well No.<br>128          |

Surface Location

|               |               |                 |              |                   |                 |                  |                 |               |
|---------------|---------------|-----------------|--------------|-------------------|-----------------|------------------|-----------------|---------------|
| UL - Lot<br>H | Section<br>23 | Township<br>17S | Range<br>34E | Feet from<br>2005 | N/S Line<br>FNL | Feet From<br>535 | E/W Line<br>FEL | County<br>Lea |
|---------------|---------------|-----------------|--------------|-------------------|-----------------|------------------|-----------------|---------------|

Well Status

|             |         |           |                |      |
|-------------|---------|-----------|----------------|------|
| Well Status | SHUT-IN | PRODUCING | DATE<br>3/1/18 | INTJ |
|-------------|---------|-----------|----------------|------|

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:


|                      | (A)Surf-Interm | (B)Interm(1)-Interm(2) | (C)Interm-Prod | (D)Prod Csg | (E)Tubing |
|----------------------|----------------|------------------------|----------------|-------------|-----------|
| Pressure             | 0              | ✓                      | ✓              | 0           | 42.50     |
| Flow Characteristics |                |                        |                |             |           |
| Puff                 | Y / N          | Y / N                  | Y / N          | Y / N       |           |
| Steady Flow          | Y / N          | Y / N                  | Y / N          | Y / N       |           |
| Surges               | Y / N          | Y / N                  | Y / N          | Y / N       |           |
| Down to nothing      | Y / N          | Y / N                  | Y / N          | Y / N       |           |
| Gas or Oil           | Y / N          | Y / N                  | Y / N          | Y / N       |           |
| Water                | Y / N          | Y / N                  | Y / N          | Y / N       |           |

If bradenhead flowed water, check all of the descriptions that apply:

|       |       |       |        |       |
|-------|-------|-------|--------|-------|
| CLEAR | FRESH | SALTY | SULFUR | BLACK |
|-------|-------|-------|--------|-------|

Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2

|                                                                                                  |                           |
|--------------------------------------------------------------------------------------------------|---------------------------|
| Signature<br> | OIL CONSERVATION DIVISION |
| Printed name: Andrew Barrientos                                                                  | Entered into RBDMS        |
| Title: Lease Operator                                                                            | Re-test                   |
| E-mail Address: mbarrientos@ctfieldservs.com                                                     |                           |
| Date: 3/1/18                                                                                     |                           |
| Phone: 575-441-1634                                                                              |                           |
| Witness:      |                           |