

HOBBS OCD

MAR 02 2018

RECEIVED

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office  
BRADENHEAD TEST REPORT

|                                           |                          |
|-------------------------------------------|--------------------------|
| Operator Name<br>Cross Timber Energy, LLC | API Number<br>3002502319 |
| Property Name<br>New Mexico BO State      | Well No.<br>2            |

7. Surface Location

|               |               |                 |              |                   |                 |                  |                 |               |
|---------------|---------------|-----------------|--------------|-------------------|-----------------|------------------|-----------------|---------------|
| UL - Lot<br>I | Section<br>12 | Township<br>18S | Range<br>34E | Feet from<br>1980 | N/S Line<br>FSL | Feet From<br>330 | E/W Line<br>FEL | County<br>Lea |
|---------------|---------------|-----------------|--------------|-------------------|-----------------|------------------|-----------------|---------------|

Well Status

|                       |               |                  |                 |
|-----------------------|---------------|------------------|-----------------|
| Well Status<br>Active | SHUT-IN<br>NO | PRODUCING<br>OIL | DATE<br>2/28/18 |
|-----------------------|---------------|------------------|-----------------|

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

|                      | (A)Surf-Interm | (B)Interm(1)-Interm(2) | (C)Interm-Prod | (D)Prod Csg | (E)Tubing |
|----------------------|----------------|------------------------|----------------|-------------|-----------|
| Pressure             | 0              |                        | —              | 35          | 110       |
| Flow Characteristics |                |                        |                |             |           |
| Puff                 | Y / N          | Y / N                  | Y / N          | Y / N       |           |
| Steady Flow          | Y / N          | Y / N                  | Y / N          | Y / N       |           |
| Surges               | Y / N          | Y / N                  | Y / N          | Y / N       |           |
| Down to nothing      | Y / N          | Y / N                  | Y / N          | Y / N       |           |
| Gas or Oil           | Y / N          | Y / N                  | Y / N          | Y / N       |           |
| Water                | Y / N          | Y / N                  | Y / N          | Y / N       |           |

If bradenhead flowed water, check all of the descriptions that apply:

|       |       |       |        |       |
|-------|-------|-------|--------|-------|
| CLEAR | FRESH | SALTY | SULFUR | BLACK |
|-------|-------|-------|--------|-------|

Remarks:

INJECTING AT THIS TIME \_\_\_ WTR, \_\_\_ GAS, \_\_\_ CO2

|                                                    |                           |
|----------------------------------------------------|---------------------------|
| Signature: <i>Al Lujan</i>                         | OIL CONSERVATION DIVISION |
| Printed name: <i>Al Lujan</i>                      | Entered into RBDMS        |
| Title: <i>Lease Operator</i>                       | Re-test                   |
| E-mail Address: <i>AlLujan@ctfieldservices.com</i> |                           |
| Date:                                              |                           |
| Phone: <i>575-441-1638</i>                         |                           |
| Witness: <i>[Signature]</i>                        |                           |