

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

MAR 22 2018

BRADENHEAD TEST REPORT

Operator Name TARGA MIDSTREAM	API Number 30-025-01195
Property Name MAUD SAUNDERS.	Well No. 4

7. Surface Location

UL - Lot L	Section 34	Township 14S	Range 33E	Feet from 1815	N/S Line S	Feet From 660	E/W Line W	County LEA
---------------	---------------	-----------------	--------------	-------------------	---------------	------------------	---------------	---------------

Well Status

TA'D Well YES <u>NO</u>	SHUT-IN YES <u>NO</u>	INJECTOR INJ <u>SWD</u>	PRODUCER OIL GAS	DATE 3-22-18
----------------------------	--------------------------	----------------------------	---------------------	-----------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0	0	0	0	700
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 <u> </u>
Steady Flow	Y / <u>0</u>	Y / <u>0</u>	Y / N	Y / <u>0</u>	WTR <u> </u>
Surges	Y / <u>0</u>	Y / <u>0</u>	Y / N	Y / <u>0</u>	GAS <u> </u>
Down to nothing	Y / N	Y / N	Y / N	Y / N	If applicable type
Gas or Oil	Y / <u>0</u>	Y / <u>0</u>	Y / N	Y / <u>0</u>	fluid injected for
Water	Y / <u>0</u>	Y / <u>0</u>	Y / N	Y / <u>0</u>	Waterflood

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <u>Randy A. Duncan</u>	OIL CONSERVATION DIVISION
Printed name: <u>Randy A. Duncan</u>	Entered into RBDMS
Title: <u>Plant Manager</u>	Re-test <u> </u>
E-mail Address: <u>rduncan@Targa resources.com</u>	
Date: <u>3-22-18</u>	
Phone: <u> </u>	
Witness: <u>KERRY FORTNER - OCD</u>	

399-3221