

5-17-18

District 1
1625 N. French Dr., Hobbs, NM 88240
Phone (575) 393-6161 Fax (575) 393-0720

HOBBS OCD
MAR 26 2018
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name VACUUM GLORIETA WEST UNIT	API Number 30-025-21637
Property Name Chevron USA	Well No. 87

7. Surface Location

UL - Lot J	Section 36	Township 17S	Range 34E	Feet from 2090	N/S Line S	Feet From 2086	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

Well Status ACTIVE	SHUT-IN NO	PRODUCING oil	DATE 3-8- /2018
------------------------------	----------------------	-------------------------	---------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure		0	n/a	80	150
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:


CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

*Lang needs to replace surf.
csg. valve.*

Lang replaced valve - re-tested 3-21-18 and passed

Signature: 	OIL CONSERVATION DIVISION
Printed name: Ruben Rodriguez	Entered into RBDMS
Title: FIELD SPECIALIST	Re-test 
E-mail Address: TZCL@CHEVRON.COM	
Date: /2018	
Phone: 575-513-5526	
Witness: <i>Gay Robinson</i>	