

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD
MAR 26 2018
RECEIVED

BRADENHEAD TEST REPORT

Operator Name VACUUM GLORIETA WEST UNIT	API Number 30-025- 29919
Property Name Chevron USA	Well No. 99H

7. Surface Location

U/L - Lot M	Section 36	Township 17S	Range 34E	Feet from 990	N/S Line S	Feet From 990	E/W Line W	County LEA
----------------	---------------	-----------------	--------------	------------------	---------------	------------------	---------------	---------------

Well Status

Well Status ACTIVE	SHUT-IN No	PRODUCING oil	DATE 3-3- /2018
-----------------------	---------------	------------------	--------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA


If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0	0	N/A	400	360
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	Y / N
Steady Flow	Y / N	Y / N	Y / N	Y / N	Y / N
Surges	Y / N	Y / N	Y / N	Y / N	Y / N
Down to nothing	Y / N	Y / N	Y / N	Y / N	Y / N
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Y / N
Water	Y / N	Y / N	Y / N	Y / N	Y / N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

Signature: 	OIL CONSERVATION DIVISION
Printed name: Ruben Rodriguez	Entered into RBDMS
Title: FIELD SPECIALIST	Re-test
E-mail Address: TZCL@CHEVRON.COM	
Date: /2018	
Phone: 575-513-5526	
Witness: 