State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Mack energy								30-025-38990 API Number			
Property Name OHIO ST								Well No.			
					7. Surface Locati	on					
		Township 18			Feet from 1650		S Line S	Feet From 1650	E/W Line W	County LEA	
					Well Status						
TA'D Well			SHUT-IN		INJECTOR			RODUCER		DATE	
YES NO) 1	YES NO		INJ S		GA GA		3-27~2/24/18		
					OBSERVED DA	ATA					
		(A)S	(A)Surf-Interm		(B)Interm(1)		(C)Interm(2)		od Csng	(E)Tubing	
Pressure				1-	0	N/A			30 50	· 85-	
Flow Characteristics			_								
Puff			Y/N		Y / N		Y/N		Y / N	CO2	
Steady F			Y7 ()		Y / N		Y/N		Y/N	WTR	
Surge			Y / (5)		Y / N		Y / N		Y / N	GAS	
Down to no					Y / N		Y/N		Y/N Y/N	If applicable type fluid injected for	
Gas or Oil Water			Y/O		Y / N Y / N	Y / N Y / N			Y/N	Waterflood	
Wate			170			17.13		1 / 1			
If bradenhead	flowed wa	ter, check a	ll of the descripti	ons that a	pply:						
CLEAR		FR	ESH		SALTY SUL		SULFU	UR BLACK			
Remarks: Pi	ease state	ior each st	ring (A,B,C,D,	E) pertino	ent information rega	ding ble	ed down o	r continuous bui	id up if applies	.	
Signature:								OIL CONSERVATION DIVISION			
Printed name:								Entered into RBDMS			
Title:								Re-test			
E-mail Addre									1		
Date 3	27-1	18	Phone:							1	
Witness: KERRY FORTNER									9		
										*	