

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name VACUUM GLORIETA WEST UNIT	API Number 30-025- 21364
Property Name Chevron USA	Well No. 13

HOBBS OCD
MAR 26 2018
RECEIVED

7. Surface Location

UL - Lot C	Section 25	Township 17S	Range 34E	Feet from 660	N/S Line N	Feet From 2310	E/W Line W	County LEA
---------------	---------------	-----------------	--------------	------------------	---------------	-------------------	---------------	---------------

Well Status

Well Status ACTIVE	SHUT-IN NO	PRODUCING ✓	DATE 3-7- /2018	oil
-----------------------	---------------	----------------	--------------------	-----

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:



	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	40	500
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

Signature: 	OIL CONSERVATION DIVISION
Printed name: Ruben Rodriguez	Entered into RBDMS
Title: FIELD SPECIALIST	Re-test
E-mail Address: TZCL@CHEVRON.COM	
Date: 3/7 /2018	
Phone: 575-513-5526	
Witness: 