District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD
MAR 26 2018
RECEIVED

BRADENHEAD TEST REPORT

Operator Name	API Number
VACUUM GLORIETA WEST UNIT	30-025- 32262
Property Name	**Well No.**
Chevron USA	15

7. Surface Location

UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
A	25	17S	34E		807	N	971	E	LEA

Well Status

Well Status	SHUT-IN	PRODUCING	DATE	
ACTIVE	NO	(PRODUCING)	3-7- /2018	oil

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csng	(E)Tubing
Pressure	0	N/A	N/A	40	0
Flow Characteristics					
Puff	Y / (N)	Y / N	Y / N	Y / N	
Steady Flow	Y / (N)	Y / N	Y / N	Y / N	
Surges	Y / (N)	Y / N	Y / N	Y / N	
Down to nothing	(Y) / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / (N)	Y / N	Y / N	Y / N	
Water	Y / (N)	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK

Remarks: INJECTING AT THIS TIME ____ WTR, ____ GAS, ____ CO2

Well down going to T/A

Signature:	OIL CONSERVATION DIVISION
Printed name: Ruben Rodriguez	Entered into RBDMS
Title: FIELD SPECIALIST	Re-test
E-mail Address: TZCL@CHEVRON.COM	
Date: 3/7/2018 Phone: 575-513-5526	
Witness: Gary Coleman	