

HOBBS OCD
MAR 26 2018
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron U.S.A, INC	³ API Number 30025 - 33850
Property Name NEW MEXICO Q STATE	Well No. 12

7. Surface Location

UL - Lot 0	Section 25	Township 17S	Range 34E		Feet from	N/S Line	Feet From	E/W Line	County LEA
----------------------	----------------------	------------------------	---------------------	--	-----------	----------	-----------	----------	----------------------

Well Status

Well Status ACTIVE	SHUT-IN No	PRODUCING oil	DATE 3-8-18
------------------------------	----------------------	-------------------------	-----------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0	0	N/A	35	40
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

Signature: Justin Wall	OIL CONSERVATION DIVISION
Printed name: Justin Wall	Entered into RBDMS
Title: FSA	Re-test [Signature]
E-mail Address: LJMK	
Date: 3-8-18	
Phone: 575-704-6224	
Witness: Gary Robinson	