

GET / E. H. T. P. I.
HOBBBS 00D
MAR 26 2018
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CHEVRON		API Number 30-025- 33569
Property Name New Mexico 0 ST.		Well No. #39

7. Surface Location

UL - Lot	Section 36	Township 17S	Range 34E	Feet from	N/S Line	Feet From	E/W Line	County LEA
----------	----------------------	------------------------	---------------------	-----------	----------	-----------	----------	----------------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJ	INJECTOR SWD	PRODUCER ☒ OIL	GAS	DATE 3-8-2018
--	--	-----	-----------------	--	-----	-------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	250	N/A	N/A	50	10
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☐
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Surf. - blew thru needle vlv 2min. - installed gauge, had 250 psi -
blew down to zero in 5 min. thru 2"

Passed

Signature:		OIL CONSERVATION DIVISION	
Printed name: RUBEN RODRIGUEZ		Entered into RBDMS	
Title: FIELD SPECIALIST A		Re-test	
E-mail Address: TZCL@CHEVRON.COM			
Date: - 2018	Phone: 575-513-5526		
Witness: <i>Gary Robinson</i>			