HOBBS OCD

State of New Mexico

Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

MAR	2.6 2018		BRADENI	HEAD TEST	T REPORT	Γ					
	Operator Name							3. API Number			
RE	Operator Name RECEIVED Operator Name Received San Andres Unit						30-025-07245				
	Property Name Chevron Of the Vocation of the						Well No. 42				
7. Surface Location											
UL - Lot Sec	Township 185	Range 34E		Feet from 1980	N/S Line	Feet From 1980	E/W Line	County	/		
Well Status											
Well Status SHUT-IN			PRODUCING	-	3-7-18						

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csng	(E)Tubing
Pressure	0	0		140	390
Flow Characteristics				- / -	
Puff	Ø/ N	Y / 🕅	Y / N	Y / N	_
Steady Flow	Y/M	Y / 🕅	Y / N	Y / N	
Surges	Y / 👏	Y / 🕅	Y / N	Y / N	
Down to nothing	Ø/ N	∅ / N	Y / N	Y / N	
Gas or Oil	Y / 🚫	Y / 10	Y / N	Y / N	
Water	Y / (5)	Y / 16	Y / N	Y/N	

CLEAR	FRESH	SALTY	SULFUR	BLA	CK	
Remarks:			INJECTING AT THIS TIME	WTR,	GAS,	CO2

JECTING AT THIS TIME WTR, GAS,CO2
J

Signature:	=	OIL CONSERVATION DIVISION		
Printed name: Tanner DeHaan		Entered into RBDMS		
Title: FSA		Re-test 2		
E-mail Address: TZYR@Chevron.com	n			
Date: 3-7-18	Phone: 575-390-4449	()		
	Witness: Kerry Jorther - O-C)	/		
	0 000 1	25.1		

399-3221