

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

MAR 26 2018

BRADENHEAD TEST REPORT

Operator Name Chevron Crayburg San Andres Unit	API Number 30-025- 32004
Property Name Chevron USA WU	Well No. 212

7. Surface Location

UL - Lot 0	Section 1	Township 18S	Range 34E	Feet from 660	N/S Line S	Feet From 1650	E/W Line E	County Lea
---------------	--------------	-----------------	--------------	------------------	---------------	-------------------	---------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING ✓	DATE 3-7-18
-------------	---------	----------------	----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0	—	—	55	60
Flow Characteristics					
Puff	Y / 0	Y / N	Y / N	Y / N	
Steady Flow	Y / 0	Y / N	Y / N	Y / N	
Surges	Y / 0	Y / N	Y / N	Y / N	
Down to nothing	0 / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / 0	Y / N	Y / N	Y / N	
Water	Y / 0	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

Signature: 	OIL CONSERVATION DIVISION
Printed name: Tanner DeHaan	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: TZYR@Chevron.com	
Date: 3-7-18	
Phone: 575-390-4449	
Witness: Kerry Foster - OCD	

399-3221