

HOBBS OGD
RECEIVED
APR 03 2018

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CHEVRON MIDCONTINENT, L.P.	³ API Number 3002503824
Property Name LOVINGTON PADDOCK UNIT	Well No. 49

7. Surface Location

UL - Lot A	Section 1	Township 17S	Range 30E	Feet from 700	N/S Line N	Feet From 000	E/W Line E	County LEA
----------------------	---------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

Well Status ACTIVE	SHUT-IN	PRODUCING INS	DATE 3-14-18
------------------------------	---------	-------------------------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:



	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csgng	(E)Tubing
Pressure	0	0	N/A	0	1600
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

Signature: 	OIL CONSERVATION DIVISION
Printed name: Martha Kodak	Entered into RBDMS
Title: KSA	Re-test 
E-mail Address: mkodak@chevron.com	
Date: 3/14/18	
Phone: 432 955 6463	
Witness: Gary Robinson	