

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CHEVRON MIDCONTINENT, L.P.	³ API Number 30025 03913
Property Name WEST LOVINGTON UNIT	Well No. 61

7. Surface Location

UL - Lot K	Section 8	Township 17S	Range 36E	Feet from 2310	N/S Line S	Feet From 1980	E/W Line W	County LEA
----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

Well Status ACTIVE	SHUT-IN	PRODUCING INS	DATE 3-14-18
------------------------------	---------	-------------------------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA


If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0	0	N/A	0	1500
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	N / N	N / N	Y / N	N / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:	INJECTING AT THIS TIME ____ WTR, ____ GAS, ____ CO2
----------	---

Signature: 	OIL CONSERVATION DIVISION
Printed name: Martin Kolar	Entered into RBDMS
Title: FSA	Re-test 
E-mail Address: MRPF @ chevron.com	
Date: 3-14-18	
Phone: 432 955 9407	
Witness: Larry Kolar	