

HOBBSCOCD
 APR 03 2018
 RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CHEVRON MIDCONTINENT, L.P.	API Number 30025 31521
Property Name WEST LOVINGTON UNIT	Well No. 99

7. Surface Location									
UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County	
D	8	17S	36E	675	N	595	W	LEA	

Well Status

Well Status Active	SHUT-IN	PRODUCING INT	DATE 3-14-18
------------------------------	---------	-------------------------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	850
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

Signature:	OIL CONSERVATION DIVISION
Printed name: Mark FSA	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: mr6f@Chevron.com	
Date: 3-14-18	Phone: 432 959 9167
Witness: Dave Kolense	