

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CHEVRON MIDCONTINENT, L.P.	³ API Number 30025 03898
Property Name WEST LOVINGTON UNIT	Well No. 88

7. Surface Location

UL - Lot J	Section 7	Township 17S	Range 36E	Feet from 1980	N/S Line S	Feet From 1980	E/W Line E	County LEA
----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

Well Status ACTIVE	SHUT-IN	PRODUCING INTJ	DATE 3-14-18
------------------------------	---------	--------------------------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA


If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0	0	N/A	0	1100
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	N	N	Y/N	N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:	INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2
----------	--

Signature: 	OIL CONSERVATION DIVISION
Printed name: Marka Rodriguez	Entered into RBDMS
Title: ESA	Re-test 
E-mail Address: MRBE @ Chevron.com	
Date: 3-14-18	
Phone: 432 955 8467	
Witness: Dany Robinson	