

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

HOBBS OCD
APR 03 2018
RECEIVED

Operator Name CHEVRON MIDCONTINENT, L.P.	³ API Number 3002505423
Property Name LOVINGTON SAN ANDRES UNIT	Well No. 38

⁷ Surface Location

UL - Lot F	Section 10	Township 17S	Range 37E	Feet from 1050	N/S Line n	Feet From 1980	E/W Line w	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

Well Status ACTIVE	SHUT-IN	PRODUCING INS	DATE 3-13-18
------------------------------	---------	-------------------------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod Casing	(E) Tubing
Pressure		0		0	1000
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

Surf. valve would not open - ~~Surf~~ Had valve open

Passed BHT

Signature: 	OIL CONSERVATION DIVISION
Printed name: MARK FALAR	Entered into RBDMS
Title: FSA	Re-test 
E-mail Address: MARK.FALAR@chevron.com	
Date: 3-14-18	
Phone: 432 955 8967	
Witness: Darryl Robinson	