

HOBBS OCD
APR 03 2018
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CHEVRON MIDCONTINENT, L.P.	³ API Number 3002503825
Property Name LOVINGTON PADDOCK UNIT	Well No. 48

7. Surface Location

UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
B	1	17S	30E		1000	n	2080	E	LEA

Well Status

Well Status	SHUT-IN	PRODUCING ☒	DATE 7-13-18
-------------	---------	--	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure				20 psi	300psi
Flow Characteristics					
Puff	Y / ☒ N	Y / ☒ N	Y / ☒ N	Y / N	
Steady Flow	Y / ☒ N	Y / ☒ N	Y / ☒ N	Y / N	
Surges	Y / ☒ N	Y / ☒ N	Y / ☒ N	Y / N	
Down to nothing	Y / ☒ N	Y / ☒ N	Y / ☒ N	Y / N	
Gas or Oil	Y / ☒ N	Y / ☒ N	Y / ☒ N	Y / N	
Water	Y / ☒ N	Y / ☒ N	Y / ☒ N	☒ / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK ☒
-------	-------	-------	--------	---


Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2

Conceded Failure

Vac truck pulled 30 bbls of Blackwater. No slowing down or loss of pressure possible Hole in tubing

Letter written ex

Signature: 	OIL CONSERVATION DIVISION
Printed name: Martin Rodriguez	Entered into RBDMS
Title: FSP	Re-test 
E-mail Address: MRBF@Chevron.com	
Date: 3-13-18	
Phone: 432 955 8462	
Witness: Guy Johnson	