

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

HOBBS OGD
APR 05 2018
RECEIVED

Operator Name Chevron USA Inc.	API Number 30-025- 30139
Property Name New Mexico AB State	Well No. 9

7. Surface Location

U/L - Lot P	Section 6	Township 18S	Range 35E	Feet from 538	N/S Line S	Feet From 818	E/W Line E	County LEA
----------------	--------------	-----------------	--------------	------------------	---------------	------------------	---------------	---------------

Well Status

Well Status ACTIVE	SHUT-IN No	PRODUCING del	DATE 3-21-18
-----------------------	---------------	------------------	-----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA


If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0	0	N/A	10	150
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

Signature: 	OIL CONSERVATION DIVISION
Printed name: Tanner DeHaan	Entered into RBDMS
Title: FSA	Re-test 
E-mail Address: TZYR@Chevron.com	
Date: 3-21-18	
Phone: 575-390-4449	
Witness: 	