

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

HOBBS OGD  
APR 05 2018  
RECEIVED

|                                     |                            |
|-------------------------------------|----------------------------|
| Operator Name<br>Chevron USA Inc.   | API Number<br>30-025-32008 |
| Property Name<br>New Mexico L State | Well No.<br>14             |

7. Surface Location

|               |              |                 |              |                  |               |                   |               |               |
|---------------|--------------|-----------------|--------------|------------------|---------------|-------------------|---------------|---------------|
| UL - Lot<br>B | Section<br>1 | Township<br>18S | Range<br>34E | Feet from<br>810 | N/S Line<br>N | Feet From<br>1980 | E/W Line<br>E | County<br>LEA |
|---------------|--------------|-----------------|--------------|------------------|---------------|-------------------|---------------|---------------|

Well Status

|                       |               |                  |                 |
|-----------------------|---------------|------------------|-----------------|
| Well Status<br>ACTIVE | SHUT-IN<br>NO | PRODUCING<br>oil | DATE<br>3-20-18 |
|-----------------------|---------------|------------------|-----------------|

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA


If bradenhead flowed water, check all of the descriptions that apply:

|                      | (A)Surf-Interm | (B)Interm(1)-Interm(2) | (C)Interm-Prod | (D)Prod Csg | (E)Tubing |
|----------------------|----------------|------------------------|----------------|-------------|-----------|
| Pressure             | 0              | N/A                    | N/A            | 25          | 70        |
| Flow Characteristics |                |                        |                |             |           |
| Puff                 | Y / N          | Y / N                  | Y / N          | Y / N       |           |
| Steady Flow          | Y / N          | Y / N                  | Y / N          | Y / N       |           |
| Surges               | Y / N          | Y / N                  | Y / N          | Y / N       |           |
| Down to nothing      | Y / N          | Y / N                  | Y / N          | Y / N       |           |
| Gas or Oil           | Y / N          | Y / N                  | Y / N          | Y / N       |           |
| Water                | Y / N          | Y / N                  | Y / N          | Y / N       |           |

If bradenhead flowed water, check all of the descriptions that apply:

|       |       |       |        |       |
|-------|-------|-------|--------|-------|
| CLEAR | FRESH | SALTY | SULFUR | BLACK |
|-------|-------|-------|--------|-------|

Remarks: INJECTING AT THIS TIME \_\_\_ WTR, \_\_\_ GAS, \_\_\_ CO2

|                                                                                                |                           |
|------------------------------------------------------------------------------------------------|---------------------------|
| Signature:  | OIL CONSERVATION DIVISION |
| Printed name: Tanner DeHaan                                                                    | Entered into RBDMS        |
| Title: FSA                                                                                     | Re-test                   |
| E-mail Address: TZYR@Chevron.com                                                               |                           |
| Date: 3-20-18                                                                                  |                           |
| Phone: 575-390-4449                                                                            |                           |
| Witness:    |                           |