

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

|                                   |  |                             |
|-----------------------------------|--|-----------------------------|
| Operator Name<br>Chevron USA Inc. |  | API Number<br>30-025- 03101 |
| Property Name<br>State AN         |  | Well No.<br>1               |

7. Surface Location

|               |              |                 |              |                  |               |                  |               |               |
|---------------|--------------|-----------------|--------------|------------------|---------------|------------------|---------------|---------------|
| UL - Lot<br>A | Section<br>7 | Township<br>18S | Range<br>35E | Feet from<br>330 | N/S Line<br>N | Feet From<br>990 | E/W Line<br>E | County<br>LEA |
|---------------|--------------|-----------------|--------------|------------------|---------------|------------------|---------------|---------------|

Well Status

|                       |               |                  |                 |
|-----------------------|---------------|------------------|-----------------|
| Well Status<br>Active | SHUT-IN<br>no | PRODUCING<br>del | DATE<br>3-20-18 |
|-----------------------|---------------|------------------|-----------------|

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

|                      | (A)Surf-Interm | (B)Interm(1)-Interm(2) | (C)Interm-Prod | (D)Prod Csng | (E)Tubing |
|----------------------|----------------|------------------------|----------------|--------------|-----------|
| Pressure             | 0              | 0                      | N/A            | 33           | 50        |
| Flow Characteristics |                |                        |                |              |           |
| Puff                 | Y / N          | Y / N                  | Y / N          | Y / N        |           |
| Steady Flow          | Y / N          | Y / N                  | Y / N          | Y / N        |           |
| Surges               | Y / N          | Y / N                  | Y / N          | Y / N        |           |
| Down to nothing      | Y / N          | Y / N                  | Y / N          | Y / N        |           |
| Gas or Oil           | Y / N          | Y / N                  | Y / N          | Y / N        |           |
| Water                | Y / N          | Y / N                  | Y / N          | Y / N        |           |

If bradenhead flowed water, check all of the descriptions that apply:

|       |       |       |        |       |
|-------|-------|-------|--------|-------|
| CLEAR | FRESH | SALTY | SULFUR | BLACK |
|-------|-------|-------|--------|-------|

Remarks: INJECTING AT THIS TIME \_\_\_ WTR, \_\_\_ GAS, \_\_\_ CO2

|                                  |                           |
|----------------------------------|---------------------------|
| Signature: <i>Tanner DeHaan</i>  | OIL CONSERVATION DIVISION |
| Printed name: Tanner DeHaan      | Entered into RBDMS        |
| Title: FSA                       | Re-test                   |
| E-mail Address: TZYR@Chevron.com |                           |
| Date: 3-20-18                    |                           |
| Phone: 575-390-4449              |                           |
| Witness: <i>Dary Robinson</i>    |                           |