## State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

OBB	BRA	DENHEAD TES	T REPOI	RT	3. API Numbe		
Property Name Vacuum Grayburg San Andres Unit  7. Surface Location					30-025- 30798		
Property Name					Well No.		
Vacuum Grayburg San Andres Unit					147 -		
7. Surface Location							
	rnship Range	Feet from	N/S Line	Feet From	E/W Line	County	
H 2 18	85 34E	1360	N	660	E	LEA	
Well Status							
Well Status ACTIVE	SHUT-IN PRODUCING		3-22-1				
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH							
If bradenhead flowed water ch	neck all of the descriptions that	OBSERVED DAT	A				
If bradenhead flowed water, check all of the descriptions that apply:  (A)Surf-Interm (B)Interm(1)-Interm(2) (C)Interm-Prod				rod (D	)Prod Csng	(E)Tubing	
Pressure		. / .	.//		6	1900	
Flow Characteristics	0	MH	NF	<i>t</i>		1100	
Puff	Y /60	Y/N	Y	N	Y / 🔊	-	
Steady Flow	Y/Q	Y / N	Y	N	YIN	-	
Surges	Y/60	Y / N	Y	N	Y / 🔊	-	
Down to nothing	Ø/ N	Y / N	Y / N		Ø N	+	
Gas or Oil	Y /60	Y / N	Y / N		Y / 🐼	1	
Water	Y/N	Y / N	Y	N	Y (N)	1	
						1	
	nhead flowed water, check all of the descriptions that apply:						
CLEAR	FRESH	SALTY	SULFUR		BLACK		
Remarks:			INTECTING	AT THIS TIME	WTP (	GAS, CO2	
Kellal ks.			INDECTING	AT THIS TIME		37.5,	
Signature:				OIL C	OIL CONSERVATION DIVISION		
Printed name: Tanner DeHaan				Entered into	Entered into RBDMS		
Title: FSA					Re-test (		
E-mail Address: TZYR@Chevron.com					and)		
Date: 3-22-18 Phone: 575-390-4449							
Date. 7 00 10	1/1	///					
	Witness: Sacy	Kalmson					