## State of New Mexico

## Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT												
Operator Name								*API Number • 025-266 70		_		
Northeast Drinkard Unit								_				
7. Surface Location												
UL-Lot	Section 3	Township 218	Range 37E			Feet from		Line	Feet From	E/W Line	County	_
Well Status												
YES TA'D W	VELL	YES	SHUT-IN	NO	INJ	INJECTOR	SWD	OIL	PRODUCER GAS	3	DATE 3/17/18	_

## **OBSERVED DATA**

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	Ø		_	0	1/00
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	(V) N	CO2
Steady Flow	Y / 🔊	Y/N	Y/N	YIM	GAS WTR
Surges	Y / (N)	Y/N	Y/N	Y/N	Type of Fluid
Down to nothing	Y/N	Y/N	Y/N	(Y) N	Injected for Waterflood if
Gas or Oil	Y / (N)	Y/N	Y/N	Y / (N)	upplies
Water	Y/(N)	Y/N	Y/N	Y /(N)	

Γ	Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.
۱	
١	
١	
١	
١	
١	
١	
١	
١	

Signature: Tracy Cole	OIL CONSERVATION DIVISION		
Printed name: Tracy Cole	Entered into RBDMS		
Title: Pumper III	Re-test		
E-mail Address: Tracy. Cole @ apache corp. com	NA NA		
Date: 3/17/18 Phone: 575-441-5196	her her		
Witness:			