

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

APR 10 2018

RECEIVED

BRADENHEAD TEST REPORT

Operator Name STRATA	API Number 30-025-08109
Property Name Gilmore	Well No. 1

7. Surface Location

UL - Lot I	Section 21	Township 22S	Range 32E	Feet from 1980	N/S Line S	Feet From 660	E/W Line E	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D Well YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR INJ ☐ SWD ☒	PRODUCER OIL ☐ GAS ☐	DATE 4/10/18
--	--	--	---	------------------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0	—	—	0	750
Flow Characteristics					
Puff	Y / ☒ N	Y / N	Y / N	☒ / N	CO2 ☐
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / ☒ N	WTR ☐
Surges	Y / ☒ N	Y / N	Y / N	Y / ☒ N	GAS ☐
Down to nothing	☒ / N	Y / N	Y / N	☒ / N	If applicable type
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / ☒ N	fluid injected for
Water	Y / ☒ N	Y / N	Y / N	Y / ☒ N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name: Dwight Adamson	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date: 4-10-18	
Phone:	
Witness: Kerry Fortner - ocd	

399-3221