

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

APR 10 2018

RECEIVED

BRADENHEAD TEST REPORT

Operator Name STATA		API Number 30-025-26844	
Property Name CUERVO Fed		Well No. 1	

7. Surface Location									
UL - Lot J	Section 14	Township 23S	Range 32E		Feet from 1980	N/S Line S	Feet From 1980	E/W Line E	County LCA

Well Status							
TA'D WELL YES	☒ NO	SHUT-IN YES	☒ NO	INJ ☒ SWD	PRODUCER OIL	GAS	DATE 4/10/18

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod C'sng	(E)Tubing
Pressure	0	—	—	0	846
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	N	WTR —
Surges	Y / N	Y / N	Y / N	N	GAS —
Down to nothing	N / N	Y / N	Y / N	N / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	N / N	Injected for
Water	Y / N	Y / N	Y / N	N / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: [Signature]		OIL CONSERVATION DIVISION	
Printed name: Dwight Adamsan		Entered into RBDMS	
Title:		Re-test	
E-mail Address:			
Date: 4-10-18	Phone:		
Witness: Kerry Fortner-UCD			

399-3221

INSTRUCTIONS ON BACK OF THIS FORM