District I 1625 N. French Dr., Hobbs, NM 88240 Phone: (575) 393-6161 Fax: (575) 393-0720

4-11-18

Date:

Phone: 575-433-8395

Witness:

Kerru

HOBBS OCD

APR 1 2 2018

State of New Mexico

Operator Name
Texland Petroleum-Hobbs, LLC

Property Name
State 1-29

Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

RECEIVED

#09

30-025-35673

					7. Surface Locati	ion						
UL - Lot			Range 38E				S Line Feet From 1300'			E/W Line East	County Lea	
					Well Status	3		•				
Wel	Status		SHUT-IN		PRODUCING WIW			4-11-18				
	OPE	N BRADEN	HEAD AND IN		TE TO ATMOSPHI		VIDUAL	LY FOR 15 MI	NUTES	EACH		
If bradenhea	d flowed wa	ter, check al	of the descripti			IA						
			(A)Surf-Interm		B)Interm(1)-Interm(2) (C		(C)Interm-Prod		(D)Prod Csng		(E)Tubing	
Pressure	Pressure		0						D		1640	
Flow Chara	Flow Characteristics											
Put	Puff		Y/Ô		Y / N		Y / N		Y / 😿			
Steady	Flow		Y / 89		Y / N		Y / N		Y / 8>			
Surg	Surges		Y / 10		Y / N		Y / N		YI			
Down to	Down to nothing		O N		Y / N	1	Y / N		6	/ N		
Gas or	r Oil		Y / 🕅	Y / N		Y / N		V	Y / 🔗			
Water			Y / 🕅		Y / N	Y / N		N	Y / 🔊			
CLEAR	If bradenhead flowed water, CLEAR		ESH	ons that app	SALTY SULFUR		UR BLACK					
Remarks:												
0:												
Signature:	Signature: S-NVS								OIL CONSERVATION DIVISION			
Printed name:								Entered into RBDMS				
Title:								Re-test			11	
E-mail Add	E-mail Address: vsmith@texpetro.com									X		

FULTINON- ACD