

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

APR 13 2018

RECEIVED

BRADENHEAD TEST REPORT

Operator Name OXY USA	*API Number 30-025-10024 ✓
Property Name E A STICHER	Well No. #2 ✓

Surface Location

UL - Lot N	Section 4	Township 22S	Range 37E	Feet from 544	N/S Line S	Feet From 1864	E/W Line W	County LEA ✓
----------------------	---------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	------------------------

Well Status

TA'D WELL YES NO	SHUT-IN YES NO	INJECTOR INJ	SWD	PRODUCER OIL GAS	DATE 4-11-18 ✓
----------------------------	--------------------------	-----------------	-----	----------------------------	--------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0	N/A	0	N/A
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 ✓
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS ✓
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Waterflood if applies
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

T/A TEST

Signature: [Signature]	OIL CONSERVATION DIVISION
Printed name: Matt Preston	Entered into RBDMS [Signature]
Title: PT	Re-test
E-mail Address:	
Date: 04/11/2018	Witness: Dary Robinson

INSTRUCTIONS ON BACK OF THIS FORM