

State of New Mexico

Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

Ken McQueen
Cabinet Secretary

Matthias Sayer
Deputy Cabinet Secretary

Heather Riley
Division Director



Response Required - Deadline Enclosed

Field Inspection Program
"Preserving the Integrity of Our Environment"

10-May-18

ENDEAVOR ENERGY RESOURCES, LP
110 N. Marienfeld Ste 200
Midland TX 79701-9701

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

NEW MEXICO BW STATE No.004		J-16-8S-33E			30-005-10083-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/10/2018	Routine/Periodic	Mark Whitaker	Yes	No	6/29/2018	iMAW1813053224
Violations Absent Well Identification Signs (Rule 103)						
Comments on Inspection: Well sign bad (Rule 19.15.16.8). NEED TO REPLACE WELL SIGN.						
NEW MEXICO BX STATE No.002		K-16-8S-33E			30-005-10087-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/10/2018	Routine/Periodic	Mark Whitaker	Yes	No	6/29/2018	iMAW1813053614
Violations Absent Well Identification Signs (Rule 103)						
Comments on Inspection: Well sign bad (Rule 19.15.16.8). NEED TO REPLACE WELL SIGN.						

LEVICK STATE No.001

I-20-8S-33E

30-005-10122-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/10/2018	Routine/Periodic	Mark Whitaker	Yes	No	8/13/2018	iMAW1813053053
Violations						
Idle well (Rule 201)						
Comments on Inspection: Expired TA (Rule 19.15.25.13). NEED TO SUBMIT PROCEDURE TO PLUG AND ABANDON WELL OR PLACE ON PRODUCTION.						

LEVICK STATE No.003

A-20-8S-33E

30-005-10124-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/10/2018	Routine/Periodic	Mark Whitaker	Yes	No	8/13/2018	iMAW1813052623
Violations						
Absent Well Identification Signs (Rule 103)						
Gas Vent/Flare Equipment (Rules 114, 115)						
Surface Release						
Comments on Inspection: Well sign not legible (Rule 19.15.16.8). Stuffing box has leaked. Buckets, chemical drums and other debris around well. Gas flowing back thru compressor and venting at battery. NEED TO REPLACE WELL SIGN. NEED TO REMOVE EXCESS DEBRIS FROM LOCATION. NEED TO CEASE GAS VENTING AT BATTERY IMMEDIATELY.						

TOBAC SWD G No.016

G-16-8S-33E

30-005-10178-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/10/2018	Routine/Periodic	Mark Whitaker	Yes	No	8/13/2018	iMAW1813053851
Violations						
Absent Well Identification Signs (Rule 103)						
Emergency/Temporary Pits						
General Housekeeping (Rule 114)						
Comments on Inspection: Well sign not legible (Rule 19.15.16.8). Unregistered sump next to triplex pump. Unlabeled drums and plastic buckets around battery. NEED TO REPLACE WELL SIGN. NEED TO REMOVE AND PROPERLY DISPOSE OF DRUMS AND BUCKETS FROM LOCATION. NEED TO CONTACT OLIVIA YU IN THE HOBBS DISTRICT OFFICE REGARDING REMOVE OF SUMP.						

CONOCO No.001

L-15-8S-33E

30-005-20805-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/10/2018	Routine/Periodic	Mark Whitaker	Yes	No	6/29/2018	iMAW1813051861
Violations						
Absent Well Identification Signs (Rule 103)						
Comments on Inspection: Well sign (Rule 19.15.16.8). WELL SIGN NEEDS TO BE REPLACED.						

CONOCO No.002

M-15-8S-33E

30-005-20806-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/10/2018	Routine/Periodic	Mark Whitaker	Yes	No	8/13/2018	iMAW1813037049
Violations						
Absent Well Identification Signs (Rule 103)						
Idle well (Rule 201)						
Comments on Inspection: Idle well (Rule 19.15.25.8). No production reported in over 70 months. Well sign bad. NEED TO PLACE WELL ON PRODUCTION OR PLUG & ABANDON. NEED TO REPLACE WELL SIGN.						

CONOCO No.004

O-15-8S-33E

30-005-20864-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/10/2018	Routine/Periodic	Mark Whitaker	Yes	No	8/13/2018	iMAW1813052278
Violations						
Absent Well Identification Signs (Rule 103)						
General Housekeeping (Rule 114)						
Comments on Inspection: Well sign not legible (Rule 19.15.16.8). Chemical drums in pasture area to east and north of well. NEED TO REPLACE WELL SIGN. NEED TO REMOVE CHEMICAL DRUMS AND OTHER DEBRIS FROM LOCATION.						

YOAKUM**No.001**

K-15-8S-33E

30-005-20908-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/10/2018	Routine/Periodic	Mark Whitaker	Yes	No	8/13/2018	iMAW1813037927
Violations						
Surface Damage/Restoration						
Comments on Inspection: PLUGGING (Rule 19.15.25.10) DO NOT RELEASE. 3 power poles, piping anchors, sump, junction box, concrete slabs with metal protruding. NEED TO REMOVE ABOVE MENTIONED ITEMS.						

NEW MEXICO BX STATE No.007

F-16-8S-33E

30-005-20986-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/10/2018	Routine/Periodic	Mark Whitaker	Yes	No	8/13/2018	iMAW1813053390
Violations						
Absent Well Identification Signs (Rule 103)						
Idle well (Rule 201)						
Comments on Inspection: No well sign (Rule 19.15.16.8). Expired TA (Rule 19.15.25.13). NEED TO INSTALL WELL SIGN. NEED TO SUBMIT PROCEDURE TO PLUG AND ABANDON WELL OR PLACE ON PRODUCTION.						

STATE 22 No.001

D-22-8S-33E

30-005-21008-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/10/2018	Routine/Periodic	Mark Whitaker	Yes	No	6/29/2018	iMAW1813053720
Violations						
Surface Leaks/Spills						
Comments on Inspection: Water tank has overflowed. Need to submit C-141 to Olivia Yu in the Hobbs district office.						

WAKONDA STATE No.001

I-16-8S-33E

30-005-21077-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/10/2018	Routine/Periodic	Mark Whitaker	Yes	No	8/13/2018	iMAW1813036577
Violations						
Surface Damage/Restoration						
Comments on Inspection: PLUGGING (Rule 19.15.25.10) DO NOT RELEASE. Last well on lease. 3 tanks, part of walkway, power pole w/ meter base and disconnect, piping south of tanks, contaminated soil under tanks, concrete base at gas line connection. NEED TO REMOVE ABOVE MENTIONED ITEMS						

WAKONDA STATE**No.002**

P-16-8S-33E

30-005-21080-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/10/2018	Routine/Periodic	Mark Whitaker	Yes	No	8/13/2018	iMAW1813036400
Violations						
Surface Damage/Restoration						
Comments on Inspection: PLUGGING (Rule 19.15.25.10) DO NOT RELEASE. Wellhead, well sign, flowline, anchor, tires, and other debris. NEED TO REMOVE ABOVE MENTIONED ITEMS.						

NEW MEXICO BX STATE No.008

N-16-8S-33E

30-005-21104-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/10/2018	Routine/Periodic Violations Idle well (Rule 201)	Mark Whitaker	Yes	No	8/13/2018	iMAW1813053541

Comments on Inspection: Expired TA (Rule 19.15.25.13). NEED TO SUBMIT PROCEDURE TO PLUG AND ABANDON WELL OR PLACE ON PRODUCTION.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely, 

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.
*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

Rule 19.15.16.8 Sign should be legible from 50' and each sign shall show operator's name, property name, well number, location by footage, unit letter, section, township, range, and API number.