

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name VACUUM GLORIETA WEST UNIT		API Number 30-025- 31132
Property Name Chevron USA		Well No. 114H

7. Surface Location

U/L - Lot B	Section 1	Township 18S	Range 34E	Feet from 280	N/S Line N	Feet from 2080	E/W Line E	County LEA
----------------	--------------	-----------------	--------------	------------------	---------------	-------------------	---------------	---------------

Well Status

Well Status ACTIVE	SHUT-IN No	PRODUCING oil-ESP	DATE 3-21- /2018
-----------------------	---------------	----------------------	---------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA



If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0	0	N/A	50	340
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Ruben Rodriguez		Entered into RBDMS	
Title: FIELD SPECIALIST		Re-test 	
E-mail Address: TZCL@CHEVRON.COM			
Date: /2018	Phone: 575-513-5526		
Witness: 