

State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

Ken McQueen
Cabinet Secretary

Matthias Sayer
Deputy Cabinet Secretary

Heather Riley
Division Director



Response Required - Deadline Enclosed

Field Inspection Program
"Preserving the Integrity of Our Environment"

HOBBS OCD

MAY 23 2018

RECEIVED

22-May-18

XOG OPERATING LLC
1801 W. TEXAS
MIDLAND TX 79701

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

SIMS 35 STATE No.001				B-35-20S-35E	30-025-27457-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/22/2018	Routine/Periodic Violations	Mark Whitaker	Yes	No	8/25/2018	iMAW1814242248
Absent Well Identification Signs (Rule 103)						
Comments on Inspection:		Correct operator not listed on well sign and does not contain required information (Rule 19.15.16.8). NEED TO REPLACE WELL SIGN.				

SIMS 35 STATE No.002				J-35-20S-35E	30-025-27785-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/22/2018	Routine/Periodic Violations	Mark Whitaker	Yes	No	8/25/2018	iMAW1814241746
Absent Well Identification Signs (Rule 103)						
Comments on Inspection:		Correct operator not listed on well sign and does not contain required information (Rule 19.15.16.8). NEED TO REPLACE WELL SIGN.				

Rule 19.15.16.8 Sign should be legible from 50' and each sign shall show operator's name, property name, well number, location by footage, unit letter, section, township, range, and API number.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,  Mark Whittemore, P.E.S.

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240

XOG OPERATING LLC
1801 W TEXAS
MIDLAND, TX 79701



HASLER

FIRST-CLASS MAIL

\$000.47⁰

05/22/2018 ZIP 88240
012E14642224

US POSTAGE