

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

HOBBS OCD
MAY 04 2018
RECEIVED

Operator Name CHEVRON USA, INC	Well Number 30-025- 24050 ✓
Property Name NORTH VACUUM ABO WEST UNIT	Well No. 23 ✓

7. Surface Location

UL - Lot D	Section 34	Township 17S	Range 34E	Feet from 510	N/S Line N	Feet From 1660	E/W Line W	County LEA
---------------	---------------	-----------------	--------------	------------------	---------------	-------------------	---------------	---------------

Well Status

TA'D WELL ☒ YES ☐ NO	SHUT-IN ☐ YES ☒ NO	INJ ☐ INJ ☐ SWD	PRODUCER ☒ OIL ☐ GAS	DATE 3-20 - 2018 ✓
--	--	--	--	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	D	110 0	N/A	10	210 ✓
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Surf. blew for 3 min - installed gauge had 60 PSI - opened back up & bleed for 5 min to zero - re-installed gauge & did not build pres.

BHT - OK

Signature: 	OIL CONSERVATION DIVISION
Printed name: RUBEN RODRIGUEZ	Entered into RBDMS
Title: FIELD SPECIALIST	Re-test
E-mail Address: TZCL@CHEVRON.COM	
Date: 3-20 - 2018	
Phone: 575-513-5526	
Witness: 	