1625 N. French Dr., Hobbs, NM 88240 Phone: (575) 393-6161 Fax: (575) 393-0720

HOBBS OCD

State of New Mexico

Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

JUN 0 5 2013

BRADENHEAD TEST REPORT

RECE	
Hans I	A F I'M I'M
A Samuel Land of the same	VIII

,	Operator Name									^{3.} API Numb		
/	PROVIDENCE ENERGY SERVICES, INC., dba Kelton Operating								30-025-32112			
1	Property Name SKELLY PENROSE B UNIT									Well No.		
					7. Surface Locati	on						
UL - Lot	Section 5	Township 23S	Range 37E		Feet from 1420		S Line OUTH	Feet From 2614		E/W Line WEST	County LEA	
					Well Status							
Ta'	D Well		SHUT-IN		INJECTOR		PRO		RODUCING		DATE	
	No		No				Oil			05/31/2018		
If bradenheac			of the description		IATE TO ATMOSPHE OBSERVED DA pply:		VIDUALI	LY FOR 15 M	MINUTE	ES EACH		
		(A)Su	(A)Surf-Interm		(B)Interm(1)-Interm(2)		(C)Interm-Prod		(D)Prod Csng		(E)Tubing	
Pressure			N/A						24		24	
Flow Chara	cteristics											
Pufi			Y/ N		Y / N		Y / N		Y / N			
Steady 1	Flow		Y/N		Y / N		Y / N		Y - N			
	Surges		Y/N		Y/N	Y / N			Y - N			
Down to n			Y/N		Y/N	Y/N			Y/N			
Gas or			Y/N		Y / N		Y/N		Y/N			
Wate	Water		Y/N		Y / N		Y / N		Y/N			
If bradenhead	l flowed wa	ter, check all	of the description	ons that a				Т		DIACK		
CLEAR	LEAK		э п		SALTY		SULFUR		BLACK			
Remarks: Cemented to S	Surface.											
			V	Accompany								
Signature:						OIL CONSERVATION DIVISION						
Printed name	Printed name: C. DALE KELTON						Entered into RBDMS					
Title: PRES	SIDENT							Re-test			\sim	
E-mail Addr	ess: provide	enceenergy@s	suddenlink.net							1	R	
Date: 06/04/2018			Phone: 432-661-1364							/ /		

Witness: